


Flashing the board

Connect micro-USB cable from micro USB port on AndromedaBox Edge to PC host (Linux PC).

AndromedaBox Edge fastboot mode:

1).When the board is power off, press and release “power” button to turn on the board, then immediately press and hold “fastboot” button until the user LED0 is on (see below picture).

2).When the board is power on, press and release “reset” button to reboot the board, then immediately press and hold “fastboot” button until the user LED0 is on (see below picture)



Burn image In linux PC:

```
$ cd "brillo source code root"
```

```
$. build/envsetup.sh
```

```
$ lunch abox_edge-eng
```

```
$ Provision
```

Reset the board when burn finished